

## **Release Notes and Known issues for EXM software version 1.35.3.**

(Outline changes and improvements done since release 1.35.2)

### ***Bug fixes***

- UHD descrambling.
- IP insertion settings disappear after reboot.
- Web browser incompatibility (other than Explorer).
- Wrong SID number is shown in Streams in Simulcrypt.
- Improved MPEG-4 SD decoding.

### ***Known issues***

- Reboot of CAS (Cryptoguard) may require disable/enable EMM.

If you want more information about the new EXM software release or other products, just send us an email or call us:

WISI Norden AB, Teknikringen 1B, 58330 LINKÖPING

Phone: +46 (0)13 210915

E-mail: [market@wisi.se](mailto:market@wisi.se)

Web: [www.wisi.se](http://www.wisi.se)